DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.12

DAILY PROJECT JOURNAL

Prime Contractor: American Bridge/Fluor Enterprises, a JV Report No: DPJ-000527 Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island Dated: **Contractor:** 03-Dec-2007

Location: Changxing Island, Shanghai, China		
Submittals(New / Total): CWR's: /		's: / HSR's: / NCR's: /
Item	Title	Detail
1	Meetings attended	10:00 compiled and presented the FUB for this week. Because Jim, Pete,
		Jason, Keith and others were in meetings with ABF today, the FUB
		run-through was less formal than normal.
2	Meetings attended	The 13:00 Daily Meeting was cancelled today because of the other meetings.
3	Other important observations	13:00 performed a walk-through of the fabrication facilities together with
		SMR Josh Ishibashi.
		Bay 1:
		Observed OBG Deck-plate mockup. It appears that some heat-straightening
		has been performed on this plate. No work was being done on the mock-up.
		No connector plates were in place.
		Bay 2:
		Observed work proceeding on the Tower Shear beams. The bottom section

Observed work proceeding on the Tower Shear beams. The bottom section of the 114m mock-up has been tack welded together. They were starting to tack-weld the upper section together. One face plate was in place. At the Gantry location observed grinding of skin plate stiffener welds On the left side of the bay, observed a skin plate in the 80 degree position with lifting attachments welded to the top and bottom of the skin plate.

Bay 3:

They are in the process of fabricating t-stiffeners plates – observed workers tack-welding t-stiffeners to plates

Bay 7:

Observed fabrication of OBG floor beams in process. Several floor-beam panels were in various stages of having a SAW weld performed.

DAILY PROJECT JOURNAL

(Continued Page 2 of 2)

Inspected By:Dautermann,PeterQuality Assurance InspectorReviewed By:Wahbeh,MazenQA Reviewer